

TYPICAL MODIFICATION

1. THIS DSP BOARD REQUIRES THE FOLLOWING FIRMWARE VERSIONS:
   1100M & 1400M>=0.73H
   1200T>=0.83P
   FAILURE TO RUN THIS BOARD WITHOUT THE APPROPRIATE FIRMWARE MAY DAMAGE THE BOARD. INSTALL BOARD FIRST, THEN DO ANY NECESSARY SOFTWARE UPDATES.

2. TYPICAL MODIFICATION TO BE USED WHEN A SPARE SLOT IS AVAILABLE. SEE SHT 2 FOR WIRING DIAGRAM. ALTERNATE MODIFICATION TO BE USED WHEN NO SPARE SLOTS ARE AVAILABLE. SEE SHT 2 WIRING IN AN 8 SLOT SYSTEM OR SHTS 3 AND 4 FOR WIRING IN 4 SLOT SYSTEM.



ALTERNATE MODIFICATION

INSTALLATION OF REPLACEMENT DSP BOARD IN 8 SLOT BACKPLANE.

1:1
MK 17.NOV 99

70000467 1 4